



**CONTACT LIST OF NATIONAL SERVICE RESPONSIBLE FOR OIL SPILL.**

| <b>NAME OF COUNTRY</b> | <b>Focal point on oil spill</b>   | <b>INVENTORY OF OIL SPILL CAPABILITIES WITH RELEVANT ATTACHMENTS</b>  |
|------------------------|---|---|
| <b>Bahrain</b>         | <p>The President of the Supreme Council of Environment in Bahrain is:</p> <p align="center"><b>H.H Shaikh Abdulla Bin Hamad Al Khalifa.</b><br/>           Tel/Cell No: 17376699 or 17386688.<br/>           Email address: <a href="mailto:dalansari@sce.gov.bh">dalansari@sce.gov.bh</a></p> <p><b>SCEB Additional Contacts: Click <a href="#">here</a></b></p> | <p>The National Contingency Plan to Combat Oil Spills aimed at ensuring the kingdom’s constant readiness to combat oil slicks that occur from time to time in its territorial waters. The Supreme council of environment in Bahrain (SCE) is in charge of overseeing the contingency plan and is supported by a committee comprising representatives from all relevant governmental and private institutions.</p> <p>Also, coordination with neighboring countries through the Marine Emergency Mutual Aid Centre (MEMAC) to monitor and combat any oil spills that may cause threat to Bahrain’s coasts and vital facilities in its territorial waters.</p> <p>As well as the Supreme Council for the Environment hopes to involve the private sector in the operations of responding to oil spill accidents, by appointing the oil spill response company (OSRL) to help with any accident of the second or third tire that may occur in the territorial or coastal waters of the Kingdom of Bahrain's borders.</p> |
| <b>Comoros</b>         | <p>1. AUTORITE NATIONALE COMPETENTE<br/>           Ministère de l’Environnement et du Développement Nationale<br/>           RESPONSABLES AU SEIN DE L’AUTORITE<br/>           1.1. Chef de l’autorité : Secrétaire Général : SAID M'madi Bacar<br/>           Adresse EX-CEFADER / MDE<br/>           Téléphone: +269 333 16 92</p>                              | <p>Equipment available is obsolete and therefore not usable.</p>  |

|  |  |
|--|--|
| <p>Télécopie -<br/>E-Mail <a href="mailto:saidmmadibacar@gmail.com">saidmmadibacar@gmail.com</a></p> <p>1.2. Responsable en charge: Directeur de l'Environnement: Youssouf Elamine Mbechezi<br/>Adresse EX-CEFADER / MDE, BP 41 MORONI<br/>Téléphone: +269 321 94 86/773 89 94<br/>Télécopie -<br/>Mail <a href="mailto:yousouf_elamine@yahoo.fr">yousouf_elamine@yahoo.fr</a></p> <p>1.3. Responsable en charge: Coordinateur national, Directeur General de la Sécurité Civile: Col. SOILIH ABDALLAH RAFICK<br/>Adresse Ancien Aéroport d'Ikoni<br/>Téléphone: 00269 333 35 43<br/>Télécopie -<br/>Mail <a href="mailto:rafick13@hotmail.com">rafick13@hotmail.com</a></p> <p>1.4. Responsable en charge: Coordinateur Local de Préparation à la Lutte de NGAZIDJA: Assoumani Abdoulhamid<br/>Adresse Route Moroni-Itsandra<br/>Téléphone: +269 336 74 28<br/>Télécopie -<br/>Mail <a href="mailto:assoumanabdoul34@gmail.com">assoumanabdoul34@gmail.com</a></p> <p>1.5. Responsable en charge: Coordinateur Local de Préparation à la Lutte de NDZOUANI: Elamine Ismael Bacar<br/>Adresse Mutsamudu, Anjouan</p> |  |
|--|--|



|                     |   |  |
|---------------------|---|--|
|                     | <p>Téléphone: Bureaux: +269 328 45 86<br/> Télécopie -<br/> Mail<br/> 1.6. Responsable en charge: Coordinateur Local<br/> de Préparation à la Lutte de MWALI: AMBOUDI Nassuhi<br/> Adresse Ndrondroni- Mohéli<br/> Téléphone : +269 364 88 50<br/> Télécopie -<br/> Mail amboudinassuhi@yahoo.com</p> <p><b>Comoros Additional Contacts: Click <a href="#">here</a></b></p> |  |
| <b>Djibouti</b>     |   |  |
| <b>Egypt</b>        |   |  |
| <b>Eritrea</b>      |   |  |
| <b>Ethiopia</b>     | <p>Ethiopia Maritime Administration<br/> Capt Getinet Abay<br/> CEO-Maritime Administration Wing<br/> Email; <a href="mailto:getinet.esl@gmail.com">getinet.esl@gmail.com</a><br/> Tel; +251911231115</p>   | <p>As Ethiopia is not a Coastal State, they do not have yet any inventory in their custody. The Masters of ships are responsible for the inventory on each ship. Flag Inspectors check as per submitted and approved SOPEP</p> |
| <b>Jordan</b>       |   |  |
| <b>Kenya</b>        |   |  |
| <b>Madagascar</b>   |   |  |
| <b>Maldives</b>     |   |  |
| <b>Mauritius</b>    |   |  |
| <b>Mozambique</b>   |   |  |
| <b>Oman</b>         |   |  |
| <b>Saudi Arabia</b> |   |  |
| <b>Seychelles</b>   |   |  |
| <b>Somalia</b>      | <p>Mr. Abdifatah Mohamed Mohamud<br/> Director of Marine Environment Department</p>   |  |



|                                    |   |  |
|------------------------------------|---|--|
|                                    | Email: <a href="mailto:marine.env.dept@mpmt.gov.so">marine.env.dept@mpmt.gov.so</a><br><a href="mailto:info@mpmt.gov.so">info@mpmt.gov.so</a><br><a href="http://www.mpmt.gov.so">www.mpmt.gov.so</a><br><br>Tel: +252615116293 |  |
| <b>South Africa</b>                |   |  |
| <b>Sudan</b>                       |   |  |
| <b>United Republic of Tanzania</b> | Contacts as follows;<br><b>DAR-PWANI-TANZANIA:</b> Click <a href="#">here</a><br><br><b>MTWARA TANZANIA:</b> Click <a href="#">here</a><br><br><b>TANGA TANZANIA:</b> Click <a href="#">here</a>                                | <b>INVENTORY OF OIL SPILL RESPONSE EQUIPMENT:</b> Click <a href="#">here</a> |
| <b>United Arab Emirates</b>        |   |  |
| <b>Yemen</b>                       |   |  |